



Form No. 5023

SERVICE & MAINTENANCE REPORT

Work to be completed by a licensed mechanic

Date of Service	14/11/2025	Make	
Asset	D109	Model	
Rego Nbr		Serial Number	64075270
Location of job	Silverwater	Hours/Odometer	2498
Completed by	Connor Snell	Licence Number	Matthew Greenlees

Work Required	500 hour service
---------------	------------------

Work Performed	Change engine oil and filter, change fuel filter, change air cleaner, check all fluids, safety inspection and grease
----------------	--

Outstanding Work Required	
---------------------------	--

Consumables/Oils/Grease					
Consumables		Hydraulic Oil		Grease	Lithoplex
Engine Oil	15w40	Gear Oil		Coolant	
Trans Oil		Diff Oil		Enviro Costs	

Additional Job Notes	
----------------------	--

Plant Safety Check - Please tick all that have been checked:			
✓	Lights, Warning Devices, Signs etc	✓	Condition of hoods, sheaves, chains
✓	Hydraulics - leaks damage connections	✓	Cabin - controls, loose objects, seat belts, windscreen visibility
✓	Components - damage, broken	✓	Warning lights / gauges
✓	Wheel/Tracks/Tyres - loose, nuts, wear	✓	Operation of brakes, steering, controls, wipers, levers, buckets
✓	Pins - pivots, rams, lift arms, bucket pins	✓	Other - eg: fire extinguisher, electrical connections, wires etc
✓	Guards - in place, secure, warnings	✓	Environmental Spill Kit complete & available
		✓	Plant Security

✓ VIP CHECK AROUND PLANT PRIOR TO COMPLETION

Travel Time		Field Labour	2.5	Total Kilometers	
-------------	--	--------------	------------	------------------	--

SIGN OFF: I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.

Service Person Name:	Matthew Greenlees
Licence No:	Matthew Greenlees
Signature:	



Form No. 3051

SERVICE & MAINTENANCE REPORT

Work to be completed by a licensed mechanic

Date of Service	18/11/2024	Make	
Asset	D109	Model	
Rego Nbr		Serial Number	
Location of job	Yard	Hours/Odometer	2308
Completed by	Trenton Van Loon	Licence Number	Trent van Loon

Work Required	250 hour service
---------------	------------------

Work Performed	Engine oil and filter. Change outer air filter. Check cooling system. Check hydraulic oil. Top up transmission oil. Check brake fluid. Check all driveline fluids. Check and adjust fan belt. Check lug nuts. Check uni joints and bearings. Check brake hold. Check rops, extinguisher and seatbelt. Grease machine. Check lights - all ok except indicators not working. Lift cylinder leaking.
----------------	---

Outstanding Work Required	
---------------------------	--

Consumables/Oils/Grease					
Consumables	Gloves rags brake cleaner	Hydraulic Oil		Grease	1
Engine Oil	13	Gear Oil		Coolant	
Trans Oil	1	Diff Oil		Enviro Costs	

Additional Job Notes	Leaking lift cylinder- not urgent
----------------------	-----------------------------------

Plant Safety Check - Please tick all that have been checked:			
✓	Lights, Warning Devices, Signs etc	✓	Condition of hoods, sheaves, chains
✓	Hydraulics - leaks damage connections	✓	Cabin - controls, loose objects, seat belts, windscreen visibility
✓	Components - damage, broken	✓	Warning lights / gauges
✓	Wheel/Tracks/Tyres - loose, nuts, wear	✓	Operation of brakes, steering, controls, wipers, levers, buckets
✓	Pins - pivots, rams, lift arms, bucket pins	✓	Other - eg: fire extinguisher, electrical connections, wires etc
✓	Guards - in place, secure, warnings	✓	Environmental Spill Kit complete & available
		✓	Plant Security

✓ VIP CHECK AROUND PLANT PRIOR TO COMPLETION

Travel Time		Field Labour	3	Total Kilometers	
-------------	--	--------------	----------	------------------	--

SIGN OFF: I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.

Service Person Name:	Trenton Van Loon
Licence No:	Trent van Loon
Signature:	