



Form No. 5052

SERVICE & MAINTENANCE REPORT

Work to be completed by a licensed mechanic

Date of Service	17/12/2025	Make	
Asset	D114	Model	
Rego Nbr		Serial Number	55590505201A
Location of job	Penrith	Hours/Odometer	77.4
Completed by	Matthew Greenlees	Licence Number	Mvtc142355

Work Required	50 hour service
---------------	-----------------

Work Performed	Service change engine oil and oil filter change air filter inner and outer Grease nipples
----------------	---

Outstanding Work Required	
---------------------------	--

Consumables/Oils/Grease			
Consumables	Gloves rags	Hydraulic Oil	Grease
Engine Oil	10	Gear Oil	Coolant
Trans Oil		Diff Oil	Enviro Costs

Additional Job Notes	
----------------------	--

Plant Safety Check - Please tick all that have been checked:	
<ul style="list-style-type: none"> ✓ Lights, Warning Devices, Signs etc ✓ Hydraulics - leaks damage connections ✓ Components - damage, broken ✓ Wheel/Tracks/Tyres - loose, nuts, wear ✓ Pins - pivots, rams, lift arms, bucket pins ✓ Guards - in place, secure, warnings 	<ul style="list-style-type: none"> ✓ Condition of hoods, sheaves, chains ✓ Cabin - controls, loose objects, seat belts, windscreen visibility ✓ Warning lights / gauges ✓ Operation of brakes, steering, controls, wipers, levers, buckets ✓ Other - eg: fire extinguisher, electrical connections, wires etc Environmental Spill Kit complete & available Plant Security

VIP CHECK AROUND PLANT PRIOR TO COMPLETION

Travel Time		Field Labour	2	Total Kilometers	
-------------	--	--------------	----------	------------------	--

SIGN OFF: I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.

Service Person Name:	Matthew Greenlees
Licence No:	Mvtc142355
Signature:	