



Form No. 5512

SERVICE & MAINTENANCE REPORT

Work to be completed by a licensed mechanic

Date of Service	09/02/2026	Make	
Asset	X52	Model	
Rego Nbr		Serial Number	0
Location of job	Yard	Hours/Odometer	3250
Completed by	Matthew Greenlees	Licence Number	Mvtc142355

Work Required	250 hour service
---------------	------------------

Work Performed	Service replace engine oil and filter flip bucket blade grease nipple
----------------	---

Outstanding Work Required	
---------------------------	--

Consumables/Oils/Grease			
Consumables	Rags gloves	Hydraulic Oil	Grease
Engine Oil	8	Gear Oil	Coolant
Trans Oil		Diff Oil	Enviro Costs

Additional Job Notes	
----------------------	--

Plant Safety Check - Please tick all that have been checked:	
<ul style="list-style-type: none"> ✓ Lights, Warning Devices, Signs etc ✓ Hydraulics - leaks damage connections ✓ Components - damage, broken ✓ Wheel/Tracks/Tyres - loose, nuts, wear ✓ Pins - pivots, rams, lift arms, bucket pins ✓ Guards - in place, secure, warnings 	<ul style="list-style-type: none"> ✓ Condition of hoods, sheaves, chains ✓ Cabin - controls, loose objects, seat belts, windscreen visibility ✓ Warning lights / gauges ✓ Operation of brakes, steering, controls, wipers, levers, buckets ✓ Other - eg: fire extinguisher, electrical connections, wires etc ✓ Environmental Spill Kit complete & available ✓ Plant Security

VIP CHECK AROUND PLANT PRIOR TO COMPLETION

Travel Time		Field Labour	3	Total Kilometers	
-------------	--	--------------	----------	------------------	--

SIGN OFF: I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.

Service Person Name:	Matthew Greenlees
Licence No:	Mvtc142355
Signature:	



Form No. 4087

SERVICE & MAINTENANCE REPORT

Work to be completed by a licensed mechanic

Date of Service	04/08/2025	Make	
Asset	X52	Model	
Rego Nbr		Serial Number	BG214
Location of job	CMS Yard	Hours/Odometer	3031
Completed by	Matthew Greenlees	Licence Number	MVTC142355

Work Required	1000 hour service
---------------	-------------------

Work Performed	Engine oil and filter. Fuel filter. Clean water separator Check fanbelt Drain and refill hydraulic oil Changed hydraulic return filter Changed air filter Check track tension Grease machine Check cab items Top up radiator and inspect cleanliness - ok Change final drive oil
----------------	--

Outstanding Work Required	None
---------------------------	------

Consumables/Oils/Grease			
Consumables	Rags	Hydraulic Oil	40
Engine Oil	9	Gear Oil	2
Trans Oil		Diff Oil	
		Grease	1
		Coolant	
		Enviro Costs	

Additional Job Notes	
----------------------	--

Plant Safety Check - Please tick all that have been checked:			
✓	Lights, Warning Devices, Signs etc	✓	Condition of hoods, sheaves, chains
✓	Hydraulics - leaks damage connections	✓	Cabin - controls, loose objects, seat belts, windscreen visibility
✓	Components - damage, broken	✓	Warning lights / gauges
✓	Wheel/Tracks/Tyres - loose, nuts, wear	✓	Operation of brakes, steering, controls, wipers, levers, buckets
✓	Pins - pivots, rams, lift arms, bucket pins	✓	Other - eg: fire extinguisher, electrical connections, wires etc
✓	Guards - in place, secure, warnings	✓	Environmental Spill Kit complete & available
		✓	Plant Security

✓ VIP CHECK AROUND PLANT PRIOR TO COMPLETION

Travel Time		Field Labour	4	Total Kilometers	
-------------	--	--------------	----------	------------------	--

SIGN OFF: I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.

Service Person Name:	Matthew Greenlees
Licence No:	MVTC142355
Signature:	