



**Form No. 5333**

**PLANT SERVICE & MAINTENANCE REPORT**

Work to be completed by a licensed mechanic

Date of Service	02/02/2026	Make	Sumitomo
Asset	<b>X53</b>	Model	SH145-6
Location of service	Putney	Serial Number	1485
Completed by	Connor Snell	Hours	<b>4030</b>
Licence Number	MVTC142355	Service Due (hours)	4500

Work Required	2000 hour service
---------------	-------------------

Work Performed	Grease, replace engine oil and filter, check coolant, replace hydraulic oil and filters, check and clean radiator, check fan belt tension, check swing reduction gear, replace final drive gear oil, replace inner and outer air filters, replace fuel filters, replace hydraulic filters, safety inspection
----------------	--

Outstanding Work Required	
---------------------------	--

Consumables/Oils/Grease					
Consumables		Hydraulic Oil	<b>75</b>	Grease	<b>1</b>
Engine Oil	<b>17</b>	Gear Oil		Coolant	
Trans Oil		Diff Oil		Enviro Costs	

Additional Job Notes	
----------------------	--

Plant Safety Check - Please tick all that have been checked:			
✓	Lights, Warning Devices, Signs etc	✓	Condition of hoods, sheaves, chains
✓	Hydraulics - leaks damage connections	✓	Cabin - controls, loose objects, seat belts, windscreen visibility
✓	Components - damage, broken	✓	Warning lights / gauges
✓	Wheel/Tracks/Tyres - loose, nuts, wear	✓	Operation of brakes, steering, controls, wipers, levers, buckets
✓	Pins - pivots, rams, lift arms, bucket pins	✓	Other - eg: fire extinguisher, electrical connections, wires etc
✓	Guards - in place, secure, warnings	✓	Environmental Spill Kit complete & available
		✓	Plant Security

**✓ VIP CHECK AROUND PLANT PRIOR TO COMPLETION**

Travel Time		Field Labour	<b>4</b>	Total Kilometres	
-------------	--	--------------	----------	------------------	--

SIGN OFF: I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.

Service Person Name:	Matthew Greenlees
Licence No:	MVTC142355
Signature:	<i>M.G.</i>



**Form No. 2808**

**SERVICE & MAINTENANCE REPORT**

Work to be completed by a licensed mechanic

Date of Service	23/09/2024	Make	
Asset	<b>X53</b>	Model	
Rego Nbr		Serial Number	
Location of job	Yard	Hours/Odometer	<b>3517</b>
Completed by	Trenton Van Loon	Licence Number	Trenton

Work Required	500 hour service
---------------	------------------

Work Performed	Engine oil and filter Both Fuel filters and clean fuel bowl Check cooling system for leaks - ok. Clean radiator cover. Top up washer bottle. Clean fuel pump. Check swing drive oil ok. Adjust ac belt and check condition of both belts-ok. Top up hydraulic oil. Check final drive oil level- ok. Check and adjust track tension. Check cab items. Grease machine. Reset service meter. Airfilter a bit dirty. Check battery connections.
----------------	---

Outstanding Work Required	Cab filters and air filters a bit clogged
---------------------------	---

Consumables/Oils/Grease					
Consumables	<b>Gloves rags brake cleaner</b>	Hydraulic Oil	<b>20</b>	Grease	<b>1</b>
Engine Oil	<b>16</b>	Gear Oil		Coolant	
Trans Oil		Diff Oil		Enviro Costs	

Additional Job Notes	Big hole in blade skin. Continued some diag on p08 camera (repin connector)
----------------------	---

Plant Safety Check - Please tick all that have been checked:	
<ul style="list-style-type: none"> <li>✓ Lights, Warning Devices, Signs etc</li> <li>✓ Hydraulics - leaks damage connections</li> <li>✓ Components - damage, broken</li> <li>✓ Wheel/Tracks/Tyres - loose, nuts, wear</li> <li>✓ Pins - pivots, rams, lift arms, bucket pins</li> <li>✓ Guards - in place, secure, warnings</li> </ul>	<ul style="list-style-type: none"> <li>✓ Condition of hoods, sheaves, chains</li> <li>✓ Cabin - controls, loose objects, seat belts, windscreen visibility</li> <li>✓ Warning lights / gauges</li> <li>✓ Operation of brakes, steering, controls, wipers, levers, buckets</li> <li>✓ Other - eg: fire extinguisher, electrical connections, wires etc</li> <li>✓ Environmental Spill Kit complete &amp; available</li> <li>✓ Plant Security</li> </ul>

**✓ VIP CHECK AROUND PLANT PRIOR TO COMPLETION**

Travel Time		Field Labour	<b>4</b>	Total Kilometers	
-------------	--	--------------	----------	------------------	--

SIGN OFF: I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.

Service Person Name:	Trenton Van Loon
Licence No:	Trenton
Signature:	