



**Form No. 5134**

**SERVICE & MAINTENANCE REPORT**

Work to be completed by a licensed mechanic

Date of Service	05/01/2026	Make	
Asset	<b>X56</b>	Model	
Rego Nbr		Serial Number	<b>BH676</b>
Location of job	Yard	Hours/Odometer	<b>2155</b>
Completed by	Matthew Greenlees	Licence Number	Mvtc142355

Work Required	2000 hour service
---------------	-------------------

Work Performed	Service engineer oil and filter fuel filter air filter inner and outer cabin filter replace hydraulic oil and filter replace final drive oil grease nipples degrease engine
----------------	---

Outstanding Work Required	
---------------------------	--

Consumables/Oils/Grease				
Consumables	<b>Gloves rags</b>	Hydraulic Oil	<b>30l s46</b>	Grease
Engine Oil		Gear Oil		Coolant
Trans Oil		Diff Oil		Enviro Costs

Additional Job Notes	
----------------------	--

Plant Safety Check - Please tick all that have been checked:	
<ul style="list-style-type: none"> <li>✓ Lights, Warning Devices, Signs etc</li> <li>✓ Hydraulics - leaks damage connections</li> <li>✓ Components - damage, broken</li> <li>✓ Wheel/Tracks/Tyres - loose, nuts, wear</li> <li>✓ Pins - pivots, rams, lift arms, bucket pins</li> <li>✓ Guards - in place, secure, warnings</li> </ul>	<ul style="list-style-type: none"> <li>✓ Condition of hoods, sheaves, chains</li> <li>✓ Cabin - controls, loose objects, seat belts, windscreen visibility</li> <li>✓ Warning lights / gauges</li> <li>✓ Operation of brakes, steering, controls, wipers, levers, buckets</li> <li>✓ Other - eg: fire extinguisher, electrical connections, wires etc</li> <li>Environmental Spill Kit complete &amp; available</li> <li>Plant Security</li> </ul>

**VIP CHECK AROUND PLANT PRIOR TO COMPLETION**

Travel Time		Field Labour	<b>4</b>	Total Kilometers	
-------------	--	--------------	----------	------------------	--

SIGN OFF: I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.

Service Person Name:	Matthew Greenlees
Licence No:	Mvtc142355
Signature:	



**Form No. 4668**

**SERVICE & MAINTENANCE REPORT**

Work to be completed by a licensed mechanic

Date of Service	10/11/2025	Make	
Asset	<b>X56</b>	Model	
Rego Nbr		Serial Number	
Location of job	Kemps Creek	Hours/Odometer	<b>2034</b>
Completed by	Connor Snell	Licence Number	Matthew Greenlees - MVTC142355

Work Required	50 hour service
---------------	-----------------

Work Performed	Replace side glass panel on cab. Install new rear view mirror, swap out fire extinguisher for new tagged one. Safety inspection all ok.
----------------	---

Outstanding Work Required	N/A
---------------------------	-----

Consumables/Oils/Grease				
Consumables	<b>Rags, grease, blades, adhesive</b>	Hydraulic Oil		Grease
Engine Oil		Gear Oil		Coolant
Trans Oil		Diff Oil		Enviro Costs

Additional Job Notes	
----------------------	--

Plant Safety Check - Please tick all that have been checked:			
✓	Lights, Warning Devices, Signs etc	✓	Condition of hoods, sheaves, chains
✓	Hydraulics - leaks damage connections	✓	Cabin - controls, loose objects, seat belts, windscreen visibility
✓	Components - damage, broken	✓	Warning lights / gauges
✓	Wheel/Tracks/Tyres - loose, nuts, wear	✓	Operation of brakes, steering, controls, wipers, levers, buckets
✓	Pins - pivots, rams, lift arms, bucket pins	✓	Other - eg: fire extinguisher, electrical connections, wires etc
✓	Guards - in place, secure, warnings	✓	Environmental Spill Kit complete & available
		✓	Plant Security

**✓ VIP CHECK AROUND PLANT PRIOR TO COMPLETION**

Travel Time	<b>1</b>	Field Labour	<b>1</b>	Total Kilometers	<b>39</b>
-------------	----------	--------------	----------	------------------	-----------

SIGN OFF: I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.

Service Person Name:	Matthew Greenlees
Licence No:	Matthew Greenlees - MVTC142355
Signature:	