



Form No. 3899

SERVICE & MAINTENANCE REPORT

Work to be completed by a licensed mechanic

Date of Service	10/06/2025	Make	
Asset	X57	Model	
Rego Nbr		Serial Number	
Location of job	Yard	Hours/Odometer	1087
Completed by	Trenton Van Loon	Licence Number	Trent van Loon

Work Required	1000 hour service
---------------	-------------------

Work Performed	10/6/25. Inner air filter. Final drive oil. Check track tension- ok. Check fan belt tension and condition. Clean and replace primary fuel filter housing. Change hydraulic oil filter. Check cooling system condition and level - ok. Grease machine. Check cab items - ok. Replace ROPS bolts and repair holes - all ok. Reset service meter. 12/6/25. Repair lights and UHF. Engine oil and filter changed. Secondary fuel filter changed and cleaned. Hydraulic return filter changed. Changed outer airfilter.
----------------	---

Outstanding Work Required	Nil
---------------------------	-----

Consumables/Oils/Grease					
Consumables	Gloves rags brake cleaner	Hydraulic Oil	25	Grease	1
Engine Oil	8	Gear Oil	2	Coolant	
Trans Oil		Diff Oil		Enviro Costs	

Additional Job Notes	Service completed over 2 days
----------------------	-------------------------------

Plant Safety Check - Please tick all that have been checked:			
✓	Lights, Warning Devices, Signs etc	✓	Condition of hoods, sheaves, chains
✓	Hydraulics - leaks damage connections	✓	Cabin - controls, loose objects, seat belts, windscreen visibility
✓	Components - damage, broken	✓	Warning lights / gauges
✓	Wheel/Tracks/Tyres - loose, nuts, wear	✓	Operation of brakes, steering, controls, wipers, levers, buckets
✓	Pins - pivots, rams, lift arms, bucket pins	✓	Other - eg: fire extinguisher, electrical connections, wires etc
✓	Guards - in place, secure, warnings	✓	Environmental Spill Kit complete & available
		✓	Plant Security

✓ VIP CHECK AROUND PLANT PRIOR TO COMPLETION

Travel Time		Field Labour	3.75	Total Kilometers	
-------------	--	--------------	-------------	------------------	--

SIGN OFF: I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.

Service Person Name:	Trenton Van Loon
Licence No:	Trent van Loon
Signature:	

CMS Contracting & Plant Hire Pty Ltd
 ABN 73 143 852 411
 10-12 Churchill Street, SILVERWATER NSW 2128
 Ph 02 9647 1929
 Email accounts@cmscontracting.com.au
 www.cmscontracting.com.au



Form No. 1593

SERVICE & MAINTENANCE REPORT

Work to be completed by a licensed mechanic

Date	3:38 PM, 4th Apr, 2024	Make	
Asset	X57	Model	
Rego Nbr		Serial Number	
Location of job	Silverwater	Hours/Odometer	732
Completed by	Connor Snell	Licence Number	Hayden Rust

Work Required	250 hour service
---------------	------------------

Work Performed	Carry out 250 hour service, replace engine oil, engine oil filter, outer air filter and check all fluid levels, grease and safety inspection
----------------	--

Outstanding Work Required	
---------------------------	--

Consumables/Oils/Grease			
Consumables		Hydraulic Oil	4
Engine Oil	3.4	Gear Oil	
Trans Oil		Diff Oil	
		Grease	1
		Coolant	
		Enviro Costs	

Additional Job Notes	
----------------------	--

Plant Safety Check - Please tick all that have been checked:	
<ul style="list-style-type: none"> ✓ Lights, Warning Devices, Signs etc ✓ Hydraulics - leaks damage connections ✓ Components - damage, broken ✓ Wheel/Tracks/Tyres - loose, nuts, wear ✓ Pins - pivots, rams, lift arms, bucket pins ✓ Guards - in place, secure, warnings 	<ul style="list-style-type: none"> ✓ Condition of hoods, sheaves, chains ✓ Cabin - controls, loose objects, seat belts, windscreen visibility ✓ Warning lights / gauges ✓ Operation of brakes, steering, controls, wipers, levers, buckets ✓ Other - eg: fire extinguisher, electrical connections, wires etc ✓ Environmental Spill Kit complete & available ✓ Plant Security

✓ VIP CHECK AROUND PLANT PRIOR TO COMPLETION

Travel Time		Field Labour	1.5	Total Kilometers	
-------------	--	--------------	-----	------------------	--

SIGN OFF: I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.

Service Person Name:	Hayden Rust
Licence No:	Hayden Rust
Signature:	