



Form No. 5576

SERVICE & MAINTENANCE REPORT

Work to be completed by a licensed mechanic

Date of Service	02/03/2026	Make	
Asset	X59	Model	
Rego Nbr		Serial Number	Smt145n6k00bb1843
Location of job	Penrith stadium	Hours/Odometer	2005.3
Completed by	Matthew Greenlees	Licence Number	Mvtc142355

Work Required	2000 hour service
---------------	-------------------

Work Performed	Service replace engine oil and filter replace both fuel filters replace air filter inner and outer replace hydraulic fluid and 2 filters replace swing reduction gear oil replace final drive oil replace cabin air filters x2 grease nipples
----------------	---

Outstanding Work Required	
---------------------------	--

Consumables/Oils/Grease			
Consumables	Rags gloves	Hydraulic Oil	75
Engine Oil	18	Gear Oil	7
Trans Oil		Diff Oil	
		Grease	.5
		Coolant	
		Enviro Costs	

Additional Job Notes	
----------------------	--

Plant Safety Check - Please tick all that have been checked:	
<ul style="list-style-type: none"> ✓ Lights, Warning Devices, Signs etc ✓ Hydraulics - leaks damage connections ✓ Components - damage, broken ✓ Wheel/Tracks/Tyres - loose, nuts, wear ✓ Pins - pivots, rams, lift arms, bucket pins ✓ Guards - in place, secure, warnings 	<ul style="list-style-type: none"> ✓ Condition of hoods, sheaves, chains ✓ Cabin - controls, loose objects, seat belts, windscreen visibility ✓ Warning lights / gauges ✓ Operation of brakes, steering, controls, wipers, levers, buckets ✓ Other - eg: fire extinguisher, electrical connections, wires etc ✓ Environmental Spill Kit complete & available ✓ Plant Security

✓ VIP CHECK AROUND PLANT PRIOR TO COMPLETION

Travel Time		Field Labour	4.5	Total Kilometers	
-------------	--	--------------	------------	------------------	--

SIGN OFF: I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.

Service Person Name:	Matthew Greenlees
Licence No:	Mvtc142355
Signature:	



Form No. 3900

SERVICE & MAINTENANCE REPORT

Work to be completed by a licensed mechanic

Date of Service	12/06/2025	Make	
Asset	X59	Model	
Rego Nbr		Serial Number	
Location of job	Northwood	Hours/Odometer	1853
Completed by	Trenton Van Loon	Licence Number	Trenton van Loon

Work Required	Repair
---------------	--------

Work Performed	Replace cutting edge. Inspect mixer door on AC system, not cha ging to face setting, stuck on feet/head
----------------	---

Outstanding Work Required	Further inspect AC ducting
---------------------------	----------------------------

Consumables/Oils/Grease				
Consumables		Hydraulic Oil		Grease
Engine Oil		Gear Oil		Coolant
Trans Oil		Diff Oil		Enviro Costs

Additional Job Notes	
----------------------	--

Plant Safety Check - Please tick all that have been checked:	
<input checked="" type="checkbox"/> Lights, Warning Devices, Signs etc Hydraulics - leaks damage connections Components - damage, broken Wheel/Tracks/Tyres - loose, nuts, wear Pins - pivots, rams, lift arms, bucket pins Guards - in place, secure, warnings	Condition of hoods, sheaves, chains Cabin - controls, loose objects, seat belts, windscreen visibility Warning lights / gauges Operation of brakes, steering, controls, wipers, levers, buckets Other - eg: fire extinguisher, electrical connections, wires etc Environmental Spill Kit complete & available Plant Security

VIP CHECK AROUND PLANT PRIOR TO COMPLETION

Travel Time		Field Labour	4.5	Total Kilometers	
-------------	--	--------------	------------	------------------	--

SIGN OFF: I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.

Service Person Name:	Trenton Van Loon
Licence No:	Trenton van Loon
Signature:	



Form No. 3432

SERVICE & MAINTENANCE REPORT

Work to be completed by a licensed mechanic

Date of Service	04/03/2025	Make	
Asset	X59	Model	
Rego Nbr		Serial Number	
Location of job	Yard	Hours/Odometer	1525
Completed by	Trenton Van Loon	Licence Number	Trent van loon

Work Required	500 hour service
---------------	------------------

Work Performed	Engine oil and filter. Secondary Fuel filter. Primary fuel filter. Check hydraulic oil level - ok. Change final drive oil. Check swing drive oil level - ok. Check fan belt - ok. Check ac belt - ok. Check radiator hoses - ok. Clean fuel pump. Primary air filter replaced. Check radiator and oil cooler - ok. Greased machine. Clean out cab filters. Reset sevice meter. Checked cab items -ok
----------------	--

Outstanding Work Required	Replace left boom cylinder grease fitting
---------------------------	---

Consumables/Oils/Grease					
Consumables	Gloves rags brake cleaner	Hydraulic Oil		Grease	1
Engine Oil	17	Gear Oil	4	Coolant	
Trans Oil		Diff Oil		Enviro Costs	

Additional Job Notes	
----------------------	--

Plant Safety Check - Please tick all that have been checked:			
✓	Lights, Warning Devices, Signs etc	✓	Condition of hoods, sheaves, chains
✓	Hydraulics - leaks damage connections	✓	Cabin - controls, loose objects, seat belts, windscreen visibility
✓	Components - damage, broken	✓	Warning lights / gauges
✓	Wheel/Tracks/Tyres - loose, nuts, wear	✓	Operation of brakes, steering, controls, wipers, levers, buckets
✓	Pins - pivots, rams, lift arms, bucket pins	✓	Other - eg: fire extinguisher, electrical connections, wires etc
✓	Guards - in place, secure, warnings	✓	Environmental Spill Kit complete & available
		✓	Plant Security

✓ VIP CHECK AROUND PLANT PRIOR TO COMPLETION

Travel Time		Field Labour	4	Total Kilometers	
-------------	--	--------------	----------	------------------	--

SIGN OFF: I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.

Service Person Name:	Trenton Van Loon
Licence No:	Trent van loon
Signature:	