



Form No. 3559

SERVICE & MAINTENANCE REPORT

Work to be completed by a licensed mechanic

Date of Service	19/03/2025	Make	
Asset	X60	Model	
Rego Nbr		Serial Number	
Location of job	Silverwater	Hours/Odometer	754
Completed by	Connor Snell	Licence Number	Sean Dicker

Work Required	250 hour service
---------------	------------------

Work Performed	Change oil and filter, top up hydraulic oil, inspect hydraulics coolant and radiator, change fan belt as worn out, replace air filter grease, safety inspection
----------------	---

Outstanding Work Required	
---------------------------	--

Consumables/Oils/Grease					
Consumables	1	Hydraulic Oil	3	Grease	1
Engine Oil	4	Gear Oil		Coolant	
Trans Oil		Diff Oil		Enviro Costs	

Additional Job Notes	
----------------------	--

Plant Safety Check - Please tick all that have been checked:	
<ul style="list-style-type: none"> ✓ Lights, Warning Devices, Signs etc ✓ Hydraulics - leaks damage connections ✓ Components - damage, broken ✓ Wheel/Tracks/Tyres - loose, nuts, wear ✓ Pins - pivots, rams, lift arms, bucket pins ✓ Guards - in place, secure, warnings 	<ul style="list-style-type: none"> ✓ Condition of hoods, sheaves, chains ✓ Cabin - controls, loose objects, seat belts, windscreen visibility ✓ Warning lights / gauges ✓ Operation of brakes, steering, controls, wipers, levers, buckets ✓ Other - eg: fire extinguisher, electrical connections, wires etc ✓ Environmental Spill Kit complete & available ✓ Plant Security

✓ VIP CHECK AROUND PLANT PRIOR TO COMPLETION

Travel Time	1	Field Labour	2.5	Total Kilometers	
-------------	----------	--------------	------------	------------------	--

SIGN OFF: I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.

Service Person Name:	Connor Snell
Licence No:	Sean Dicker
Signature:	

CMS Contracting & Plant Hire Pty Ltd
 ABN 73 143 852 411
 10-12 Churchill Street, SILVERWATER NSW 2128
 Ph 02 9647 1929
 Email accounts@cmscontracting.com.au
 www.cmscontracting.com.au



SERVICE & MAINTENANCE REPORT

Docket # 0064

DATE: 5-1-24 MAKE: Takeuchi
 LOCATION OF JOB: Silverwater MODEL: TB215R
 PLANT NO: X60 SERIAL NO: 215002024
 REGO NO: _____ HOURS/KMS: 530

WORK REQUIRED:

500 HOUR SERVICE

WORK PERFORMED:

Change engine oil & filter
" fuel filter & water separator filter
" hydraulic oil return filter
check hydraulics, coolant, belt, radiator
grease
safety inspection
clean air cleaner

OUTSTANDING WORK REQUIRED:

CONSUMABLES: _____ HYDRAULIC OIL: 1 GREASE: 1
 ENGINE OIL: 4.3 GEAR OIL: _____ COOLANT: _____
 TRANS OIL: _____ DIFF OIL: _____ ENVIRO COSTS: _____

TRAVEL TIME		FIELD LABOUR	<u>2</u>	TOTAL KILOMETERS	
--------------------	--	---------------------	----------	-------------------------	--

PLANT SAFETY CHECK	✓
Machine Hours	
Lights, Warning Devices, Signs etc	
Hydraulics – leaks, damage, connections	
Components – damage, broken	
Wheel/Tracks/Tyres – loose, nuts, wear	
Pins – pivots, rams, lift arms, bucket pins	
Guards – in place, secure, warnings	
Condition of hoods, sheaves, chains	
Cabin – controls, loose objects, seat belts, windscreen visibility	
Warning lights/Gauges	
Operation of brakes, steering, controls, wipers, levers, buckets	
Other – e.g. Fire Extinguisher, electrical connections, wires etc	
Environmental spill kit complete & available	
Plant Security	
VIP CHECK AROUND PLANT PRIOR TO COMPLETION	

SIGN OFF

Serviceperson: Les Nicholas

Licence No.: _____

I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.

Signature: _____