



Form No. 4162

SERVICE & MAINTENANCE REPORT

Work to be completed by a licensed mechanic

Date of Service	21/08/2025	Make	
Asset	X67	Model	
Rego Nbr		Serial Number	
Location of job	Yard	Hours/Odometer	620
Completed by	Matthew Greenlees	Licence Number	Mvtc142355

Work Required	500 hour service
---------------	------------------

Work Performed	Engine oil and filter. Fuel filter. Clean water separator Check fanbelt Drain and Changed hydraulic return filter Changed air filter Check track tension Grease machine Check cab items Top up radiator and inspect cleanliness - ok
----------------	--

Outstanding Work Required	
---------------------------	--

Consumables/Oils/Grease			
Consumables	Rags gloves	Hydraulic Oil	Grease Kajo Lzr-2
Engine Oil	15w-40	Gear Oil	Coolant
Trans Oil		Diff Oil	Enviro Costs

Additional Job Notes	
----------------------	--

Plant Safety Check - Please tick all that have been checked:			
✓	Lights, Warning Devices, Signs etc	✓	Condition of hoods, sheaves, chains
✓	Hydraulics - leaks damage connections	✓	Cabin - controls, loose objects, seat belts, windscreen visibility
✓	Components - damage, broken	✓	Warning lights / gauges
✓	Wheel/Tracks/Tyres - loose, nuts, wear	✓	Operation of brakes, steering, controls, wipers, levers, buckets
✓	Pins - pivots, rams, lift arms, bucket pins	✓	Other - eg: fire extinguisher, electrical connections, wires etc
✓	Guards - in place, secure, warnings		Environmental Spill Kit complete & available
			Plant Security

VIP CHECK AROUND PLANT PRIOR TO COMPLETION

Travel Time		Field Labour	5	Total Kilometers	
-------------	--	--------------	----------	------------------	--

SIGN OFF: I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.

Service Person Name:	Matthew Greenlees
Licence No:	Mvtc142355
Signature:	



TUTT BRYANT EQUIPMENT

8 Ferngrove Place

South Granville NSW 2142

Job ID	N0006128992-1
Date	10/22/24 8:49 AM

Customer Details

Name	CMS PLANT HIRE PTY LTD
Address	50 PETER BROCK DR EASTERN CREEK
Contact	CONNOR 0425 296 245
Phone	0414 393 245

Job Details

Technician	Aidan Ward	Tech ID	N295
Job Type	Service		
Description	YANMAR SV100-2B EXCAVATOR BF731-SV1002B :- 1)INITIAL 50 HOUR SERVICE - FREE 2)COMPLETE FAULT LIST AND SERVICE REPORT 3)CHANGE ENGINE OIL, GEAR OIL IN THE MACHINE.		
Work Done	.Traveled to site As requested completed scheduled 50hr interval service. changed engine oil and oil filter check and change fuel filters check and clean air filter check and change gear oil check and top up all levels		
Recommended			
Comments			


Parts

Part #	Description	Qty
WSFO4	ENGINE OIL	10.0
NSFO2	GEAR OIL 80/90 (2135xxxx)	5.0
NSFO9	GREASE RENOLIT POPIPLEX2 (1812xxx)	2.0

Time

Normal	2.0	Overtime	0.0	Double	0.0	Travel	1.0	Total	3.0
--------	-----	----------	-----	--------	-----	--------	-----	--------------	------------

Customer Signature

Name	ben	
------	-----	--



TUTT BRYANT EQUIPMENT

8 Ferngrove Place

South Granville NSW 2142

Job ID	N0006128992-1
Date	10/22/24 8:49 AM

Risk Assessment

Risk Assessment Required For Site?	Basic Site Assessment
------------------------------------	-----------------------

Site Induction

Have you been inducted onto the site?	Yes
---------------------------------------	-----

Will you complete a take 5 before starting work ?	Yes
---	-----

Manual Handling

Consider Manual Handling	Yes
--------------------------	-----

Looking for moving objects

Look for being hit by moving objects	Yes
--------------------------------------	-----

Inspect for possible falls on the same level

Inspected for possible falls on the same level	Yes
--	-----

View work area for hitting stationary objects

Inspected work area for hitting stationary objects	Yes
--	-----

--	--

--	--



TUTT BRYANT EQUIPMENT

8 Ferngrove Place

South Granville NSW 2142

Job ID	N0006128992-1
Date	10/22/24 8:49 AM

Asset	BF731-SV1002B	Status	Serviced
--------------	---------------	---------------	----------

Asset type	YA		
------------	----	--	--

Model #		Make	
---------	--	------	--

Notes

Main Service Inspection Check-YA

Tutt Bryant Equipment

Service Call Reason	Service
---------------------	---------

Operating hours on machine at time of service	229
---	-----

Photo of current hour meter reading	Checked
-------------------------------------	---------

Installed Next Service Sticker	Yes
--------------------------------	-----

Serial Number	bf731
---------------	-------

Model Group Serviced / Inspected	Yanmar Excavator
----------------------------------	------------------

Service Interval Yanmar Excavator	250
-----------------------------------	-----

Engine

Replace Engine Oil and Filter(s)	Yes
----------------------------------	-----

Replace Fuel Filter(s)	Yes
------------------------	-----

Service Fuel Screen	Yes
---------------------	-----

Replace Outer Air Filter	No
--------------------------	----

Service Inner Air Filter	No
--------------------------	----

Inspect Radiator Coolant and Concentrate Level	Yes
--	-----

Inspect Radiator and Oil Cooler for Blockage and/or Damage	Yes
--	-----

Inspect All Belts Condition and Tension (Adjust if Required)	Yes
--	-----

Inspect for any Engine Water / Oil Leaks or Blow By	Yes
---	-----

Inspect Engine Hoses and Pipes for Damage	Yes
---	-----

Inspect Start Operation and for any Abnormal Engine Noise	Yes
---	-----

Hydraulic System

Inspect Hydraulic Oil Level (Top Up if Required)	Yes
--	-----

Inspect Components for physical damage or distortion	Yes
--	-----

Inspect Pump and Control Valve leakage, Inspect Hoses and Pipes for	Yes
---	-----

Inspect Cylinders and Hoses for Oil leakage or breakage	Yes
---	-----



TUTT BRYANT EQUIPMENT

8 Ferngrove Place
South Granville NSW 2142

Job ID	N0006128992-1
Date	10/22/24 8:49 AM

Travel System

Take Left and Right Side Final Drive Reduction Oil Sample for Analysis	Yes
Inspect Track Chain Sprockets for Damage and Wear	Yes
Inspect Upper/Lower Rollers and Idlers for Leakage and Wear	Yes
Inspect Track Chain and Shoe Condition, Wear and Tension	Yes
Inspect all Bolts are Secure and Not Broken / Missing	Yes
Inspect All Travel Speed are Operating Correctly	Yes
Replace Left and Right Side Final Drive Reduction Oils	Yes
Inspect System for abnormal noise and proper operation	Yes

Swing System

Inspect Slew Oil Level (Top Up if Required)	Yes
Inspect Swing System for Oil Leakage, Inspect Hoses and Pipes for	Yes
Inspect Components for physical damage or distortion	Yes
Grease Turntable Bearing and Inspect Seal for Placement or Damage	Yes
Inspect System for Abnormal Noise and Correct Operation	Yes

Electrical System

Inspect Horn, Buzzers and Work lights for Correct Operation	Yes
Inspect Window Wiper Arm, Blades and Motor for Wear and Correct	Yes
Inspect Battery Terminals and Cables, Inspect Electrolyte level (Top Up	Yes
Inspect Electrical Wiring for Short Circuits and Terminals are Secure	Yes
Inspect Heater and Air Conditioner Operation	Yes

Frame and Attachments

Inspect All Boom, Arm and Bucket Pins / Bushes for Wear / Damage	Yes
Grease All Points on Boom and Arm Area	Yes
Inspect Bucket and Teeth for Wear and Damage	Yes
Inspect Quick Hitch/Safety Pin operation, Inspect for leaks and	Yes
Inspect Structural Areas for Damage and Distortion	Yes
Inspect Body Panels for Damage and Distortion	Yes
Inspect Undercarriage Guards for Fitment, Damage and Distortion	Yes
Inspect Door and Window Locks, Inspect operation and for damage	Yes
Inspect OH&S Safety Decals are fitted and in place	Yes